


36" Transfer Showers: LH/RH = SEAT location.
Fixture is located opposite seat. Reference submittal sheet for details.

1363BFS








36 x 36 x 75 ¾ Interior
42 ½ x 38 ¼ x 77 Exterior
AcrylX™ applied acrylic



ANSI configuration pictured.


ADDITIONAL FEATURES

- ¾" (20 mm) skirt
- ½" (15 mm) beveled threshold
- Level base
- Barrier free when properly installed
- Smooth wall
- Center drain
- ADA, ANSI, TAS

CONFIGURATION	DRAIN	SEAT	PRICE
Base	Center		\$1,138
	Center		\$1,362
 	Center	LH/RH	\$1,989
 	Center	LH/RH	\$2,594
 	Center	LH/RH	\$2,724




1363EN

36 x 36 x 75 ¾ Interior
38 ¼ x 38 ¾ x 77 ½ Exterior
AcrylX™ applied acrylic



ADDITIONAL FEATURES

- 3" skirt
- 2" interior threshold
- Smooth wall
- Center drain

CONFIGURATION	DRAIN	SEAT	PRICE
Base	Center		\$1,057
2 x 	Center		\$1,373
2 x  	Center	LH/RH	\$2,000

ADDITIONAL INFO

COLORS

STOCK

White

UPGRADED

Almond*

Biscuit

Bone*

*Available on AcrylX™ models only.

Aquatic reserves the right to discontinue models, colors, options and trim finishes without notice.

OPTIONS PRICE LIST	PRICE
AcrylX™ Stock color	No charge
AcrylX™ Upgraded color	\$35
L-shaped grab bar: 18" x 32"	\$224
Straight grab bar: 18"	\$130
L-shaped fold-up seat - cushioned (stock)	\$627
L-shaped fold-up seat - phenolic white or phenolic teak	\$652
Pressure balancing mixing valve	\$312
Handheld shower assembly with slide bar	\$293
Shower curtain for 36" curtain rod	\$70
Stainless steel curtain rod: 36"	\$52
Brass drain	\$32
Soap dish - stainless steel	\$82
Finish repair kit	\$198
Grab bar reinforcement - per wall (all flat surfaces)	\$58
Crating	\$440
* Additional grab bars available. See page 158.	

OPTIONS PRICE LIST	PRICE
AcrylX™ Stock color	No charge
AcrylX™ Upgraded color	\$35
Straight grab bar: 24" (ea.)	\$158
Single fold-up seat - cushioned (stock)	\$627
Single fold-up seat - phenolic white or phenolic teak	\$652
Pressure balancing mixing valve	\$312
Handheld shower assembly with slide bar	\$293
Shower curtain for 42" curtain rod	\$87
Stainless steel curtain rod: 42"	\$61
Brass drain	\$32
Soap dish - stainless steel	\$82
Finish repair kit	\$198
Grab bar reinforcement - per wall (all flat surfaces)	\$58
Crating	\$440
* Additional grab bars available. See page 158.	