

PowerPEX™**3/8" F1807 PEX Branches****3/4" F1807 PEX × Spin Closed Trunk**

- 1" Type L copper trunk
- Branches are 2" on-center



Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
671X0490	4	3/8" F1807	B	25	25
671X0690	6	3/8" F1807	B	25	25
671X0890	8	3/8" F1807	B	25	25
671X1090	10	3/8" F1807	B	25	25
671X1290	12	3/8" F1807	B	25	25

**NO
LEAD****PowerPEX™****3/8" F1807 PEX Branches****3/4" Male Sweat × Spin Closed Trunk**

- 1" Type L copper trunk
- 3/4" male sweat connection provides flexibility
- Branches are 2" on-center



Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
671X0430	4	3/8" F1807	B	25	25
671X0630	6	3/8" F1807	B	25	25
671X0830	8	3/8" F1807	B	25	25
671X1030	10	3/8" F1807	B	25	25
671X1230	12	3/8" F1807	B	25	25

**NO
LEAD****PowerPEX™****1/2" F1807 PEX Branches****3/4" F1807 PEX × 3/4" F1807 PEX Trunk**

- 1" Type L copper trunk
- Branches are 2" on-center
- Great as a primary manifold



Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
672X0399	3	1/2" F1807	B	25	25
672X0499	4	1/2" F1807	B	25	25
672X0499PK	4	1/2" F1807	C*	6	6
672X0599	5	1/2" F1807	B	25	25
672X0699	6	1/2" F1807	B	25	25
672X0699PK	6	1/2" F1807	C*	6	6
672X0899	8	1/2" F1807	B	25	25
672X0999	9	1/2" F1807	B	25	25
672X1299	12	1/2" F1807	B	25	25

**NO
LEAD**