

**PowerPEX™****1/2" F1807 PEX Branches****1" F1807 PEX × Spin Closed Trunk**

- 1" Type L copper trunk
- Branches are 2" on-center

**NO
LEAD**

Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
672X0470	4	1/2" F1807	B	10	10
672X0670	6	1/2" F1807	B	10	10
672X0870	8	1/2" F1807	B	10	10
672X1270	12	1/2" F1807	B	10	10

**PowerPEX™****1/2" F1807 PEX Branches****3/4" Male Sweat ×****3/4" Male Sweat Extended Trunk**

- 1" Type L copper trunk
- Branches are 2" on-center
- Extended ends can be easily converted to 1" male sweat by cutting off the reduction or spin closed end, leaving 5" from PEX branch

**NO
LEAD**

Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
672X0433EE	4	1/2" F1807	B	10	10
672X0633EE	6	1/2" F1807	B	10	10
672X0833EE	8	1/2" F1807	B	10	10
672X1033EE	10	1/2" F1807	B	10	10
672X1233EE	12	1/2" F1807	B	10	10

**PowerPEX™****1/2" F1807 PEX Branches****3/4" Male Sweat ×****3/4" Female Sweat Trunk**

- 1" Type L copper trunk
- Branches are 2" on-center

**NO
LEAD**

Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
672X0431PK	4	1/2" F1807	C*	5	5